

## Vancouver schools in the Seismic Mitigation Program: losses under current area standards

School	Proposal	Stage	Losses
<b>Van Tech Secondary</b>	Renovation	Construction	<ul style="list-style-type: none"> <li>• <b>Floor area:</b> lost a 3000m<sup>2</sup> wing.</li> </ul>
<b>Dickens</b>	Replacement	Construction	<ul style="list-style-type: none"> <li>• <b>Floor area:</b> total reduced by one third</li> <li>• <b>Playing field area</b> reduced by at least one third (and previously too small).</li> <li>• <b>Community amenity space:</b> 800m<sup>2</sup> (1913 wing) will potentially be torn down.</li> <li>• <b>Music room</b> housed in vacant classroom - potential for loss if school fills to capacity.</li> <li>• <b>Playground equipment</b> lost.</li> </ul>
<b>Cook</b>	Renovation	Construction (Tender)	<ul style="list-style-type: none"> <li>• <b>Playground equipment</b> lost.</li> </ul>
<b>Trafalgar</b>	Renovation	Construction (Contract)	<ul style="list-style-type: none"> <li>• <b>Childcare area</b> lost – no space in renovated school building.</li> </ul>
<b>Moberly</b>	Renovation	Construction (Contract)	Not losing any facilities.
<b>Gordon</b>	Replacement	DDR (Bylaw)	<ul style="list-style-type: none"> <li>• <b>Floor area:</b> total reduced by one third.</li> <li>• <b>Multipurpose area used for childcare</b> will be reduced by 80%. Too small to support the 60-student program (which already has a 15-student wait list).</li> <li>• <b>Lunchroom</b> area reduced by 60%. Will be insufficient for 380-student body.</li> <li>• <b>Outdoor covered play areas</b> and <b>playground equipment</b> lost.</li> <li>• <b>Stage</b> lost.</li> <li>• <b>Library area</b> reduced from 240 SM to 180: area insufficient for dual-language facility.</li> </ul>
<b>Kitchener</b>	Replacement of main school. Renovation of wood frame building	DDR (Bylaw)	<ul style="list-style-type: none"> <li>• <b>Floor area:</b> total reduced by one quarter.</li> <li>• <b>Multipurpose area used for childcare</b> reduced by 65%: new area insufficient to support the license for the 40-student child care program.</li> <li>• <b>Library area</b> 25% smaller.</li> <li>• <b>Indoor rainy day play area</b> lost.</li> </ul>
<b>Douglas</b>	Replacement	DDR (Bylaw)	No public process: very little communication and no consultation by the VSB for the past 2 years. Recent announcement that the MoE have approved a replacement school has spurred a meeting with the VSB.
<b>Secord</b>	Renovation.	DDR (With MoE)	<ul style="list-style-type: none"> <li>• <b>Floor area:</b> total will be reduced by about one third.</li> <li>• <b>Multipurpose area used for childcare</b> lost. New 100m<sup>2</sup> multipurpose area will not be able to support even half of the 40-student child care program.</li> <li>• <b>Lunchroom area:</b> reduced, which is already used in shifts to accommodate all students. New space will not support the <b>hot lunch program</b>, essential for the inner-city student population.</li> <li>• <b>Gym/auditorium:</b> second gym space will be lost, essential for the 680-student body.</li> </ul>
<b>Kitsilano Secondary</b>		Feasibility study	<ul style="list-style-type: none"> <li>• <b>Gym and auditorium:</b> lost in lowest cost proposal.</li> </ul>
<b>L'Ecole Bilingue</b>		Feasibility study	No public process: no communication from the VSB for 2 years.